

Operator: Extraction Oil and Gas

Location Name: Breniman 16-B

Loc ID: 439436

Inspection: 697008060



Exhibit A



Exhibit B



Exhibit C

CA: All crude oil and produced water tank's contents/capacity placards have faded and are illegible. Maintenance tank lacks contents and capacity placards, see attached photos. Install signs to comply with Rule 605.h.

CA Resolution: All crude oil and produced water tank's contents/capacity placards have been replaced and new signage has been installed to the maintenance tanks to comply with rule 605.h.