

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NWNE

Location ID: 335274

Date: 10/13/2023



Oct 13, 2023 at 15:02:19



Oct 13, 2023 at 15:03:11

Location Entrance – Photo #06911

Wellheads – Photo #06912



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NWNE

Location ID: 335274

Date: 10/13/2023



Separators – Photo #06916



Tank Battery – Photo #06915



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NWNE

Location ID: 335274

Date: 10/13/2023



**Lack of Stabilization/Insufficient Vehicle Tracking BMPs –  
Photo #06913**



**Lack of Stabilization/Insufficient Vehicle Tracking BMPs –  
Photo #06914**