

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NENE

Location ID: 323870

Date: 10/13/2023



Location Entrance – Photo #06918



NE Corner of Location – Photo #06919

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NENE

Location ID: 323870

Date: 10/13/2023



Wellhead – Photo #06922



Separators – Photo #06924

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NENE

Location ID: 323870

Date: 10/13/2023



Tank Battery – Photo #06923



Unprotected Soil Stockpile – Photo #06920

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NENE

Location ID: 323870

Date: 10/13/2023



Unprotected Soil Stockpile – Photo #06921