

# Interim Reclamation and Stormwater Inspection

October 4, 2023

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462919

Inspection Document #: 697504886

Weld County, CO

SESE Section 21 T11N R64W

Chris Binschus  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Little Lady 21/South Well Pad  
Location ID: 462919



**Photo 1.** Photo taken from the southeastern location, facing North. Photo illustrates much of the vegetative growth to be an introduced grass species, which was falsely reported to Staff, and is in the process of senescing. There is a lack of desirable germination throughout the interim area.

Cereal rye was still observed throughout portions of the interim reclamation area.



**Photo 2.** Photo taken from the southeastern location, facing West. See comments under Photo 1.

Inspection Photos

Location Name: Little Lady 21/South Well Pad

Location ID: 462919



**Photo 3.** Photo taken from the southern location, facing West. See comments under Photo 1.



**Photo 4.** Photo taken from the southern location, facing East. Photo illustrates a portion along the southern interim area where the introduced grass was not seeded and how native, desirable vegetation has established.



## Inspection Photos

Location Name: Little Lady 21/South Well Pad

Location ID: 462919



**Photo 5.** Photo taken from the eastern topsoil stockpile. Photo illustrates what appears to be cultivated millet, which should not persist. If this turns out to be Wild proso millet, then this is problematic and is a List C Colorado noxious weed.



**Photo 6.** Close up photo of what appears to be cultivated millet.



Inspection Photos  
Location Name: Little Lady 21/South Well Pad  
Location ID: 462919



**Photo 7.** Photo taken from the topsoil stockpile, facing East. Photo illustrates desirable vegetation that is in process of establishing. There are bare patches that will still need to be reseeded.



**Photo 8.** Photo taken from the eastern topsoil stockpile, facing East. Photo illustrates bare patches that will still need to be reseeded.

