

Interim and Stormwater Inspection

October 9, 2023

Operator: Investment Equip. LLC, #10330

Location ID: 319634

Inspection Document #:709400532

Adams county, CO

NWNE, Section 22, 2S 57W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. Photo taken of location sign, facing south

Inspection Photos
Location Name: Clifford Causey 17
Location ID: 319634

Oct 9, 2023 at 12:46:56 PM
Fort Morgan CO 80701
United States



Photo 2. Photo taken of of wellhead, facing northwest.

Oct 9, 2023 at 12:46:59 PM
Fort Morgan CO 80701
United States



Photo 3. Photo taken of reclaimed area around wellhead, with weeds (kochia) & perennial grasses facing west.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 709400532

Inspection Photos

Location Name: Clifford Causey 17

Location ID: 319634

Oct 9, 2023 at 12:48:27 PM
Fort Morgan CO 80701
United States



Photo 4. Photo taken facing southeast of weeds (kochia) in reclaimed area around working area of wellhead at entrance of site.

Sep 7, 2023 at 3:37:28 PM
Fort Morgan CO 80701
United States



Photo 5. Photo taken facing northeast of weeds (kochia), and bare soil in reclaimed area. Little to no perennial grasses observed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 709400532



Photo 6. Photo taken facing south of cocklebur weeds on site.



Photo 7. Photo taken facing northeast of undisturbed area for reference vegetation comparison.

Inspection Photos

Location Name: Clifford Causey 17

Location ID: 319634

Sep 7, 2023 at 2:58:50 PM
Fort Morgan CO 80701
United States



Photo 8. Photo taken of location sign.
Tank battery ID 319632.

Sep 7, 2023 at 2:59:04 PM
Fort Morgan CO 80701
United States



Photo 9. Photo taken of battery, facing south. This
is an off location tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 709400532



Photo 10. Photo taken facing north, of large gully with exposed un-stabilized flowlines