

# Final Reclamation Inspection

September 13, 2023

Operator: Noble Energy # 100322

Location ID: 460169

Inspection Document #:709400558

Weld, County CO

NWSW, Section 1 3N67W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: H 03-10 Pad  
Location ID: 460169

Sep 13, 2023 at 12:57:48 PM  
La Salle CO 80645  
United States




Photo 1. Photo taken of location sign.

Sep 13, 2023 at 12:58:32 PM  
La Salle CO 80645  
United States



Photo 2. Photo taken facing northwest of entrance of new pad construction.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 709400558



**Inspection Photos**  
**Location Name: H 03-10 Pad**  
**Location ID: 460169**

Sep 13, 2023 at 12:58:49 PM  
La Salle CO 80645  
United States



**Photo 3. Photo taken facing north of cut slope west side of location and topsoil stockpile on the north side of location.**

Sep 13, 2023 at 1:02:03 PM



**Photo 4. Photo taken facing north of area between access road and cut slope west side of pad, and topsoil stockpile on the north side of location.**



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**  
Department of Natural Resources

Inspection Number: 709400558



Inspection Photos  
Location Name: H 03-10 Pad  
Location ID: 460169

Sep 13, 2023 at 1:02:35 PM  
La Salle CO 80645  
United States



**Photo 5. Photo taken of topsoil stockpile on north side of location. Photo taken facing northwest.**

Sep 13, 2023 at 1:02:56 PM  
La Salle CO 80645  
United States



**Photo 6. Photo taken of topsoil stockpile on north side of location. Photo taken facing west.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 709400558



Inspection Photos  
Location Name: H 03-10 Pad  
Location ID: 460169



**Photo 7. Photo taken of wattles at edge of disturbance on the north side of location. Photo taken facing west.**



**Photo 8. See photo 7 comments.**



**Inspection Photos**  
**Location Name: H 03-10 Pad**  
**Location ID: 460169**



**Photo 9. Photo taken of location under construction from atop topsoil stockpile. Photo taken facing southwest.**



**Photo 10. Photo taken of location under construction from atop trackwalked topsoil stockpile. Photo taken facing west.**



Inspection Photos  
Location Name: H 03-10 Pad  
Location ID: 460169

Sep 13, 2023 at 1:05:44 PM  
La Salle CO 80645  
United States



**Photo 11. Photo taken of trackwalked topsoil stockpile on north side of location Photo taken facing east.**

Sep 13, 2023 at 1:06:09 PM  
La Salle CO 80645  
United States



**Photo 12. Photo taken of sediment trap under construction on the west side of location. Photo taken facing south.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 7094005588



**Inspection Photos**  
**Location Name: H 03-10 Pad**  
**Location ID: 460169**



**Photo 13. Photo taken of wattles on west side of location perimeter. Photo taken facing south.**



**Photo 14. Photo taken of pad under construction. Photo taken facing northeast.**



Inspection Photos  
Location Name: Cornelius 11-22  
Location ID: 332721

Sep 13, 2023 at 1:10:56 PM  
La Salle CO 80645  
United States



**Photo 15. Photo taken of wattles on south side of location perimeter. Photo taken facing west.**

Sep 13, 2023 at 1:11:27 PM  
La Salle CO 80645  
United States



**Photo 16. Photo taken photo of proposed wells on pad. Photo taken facing north.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 709400558