

Interim Reclamation and Stormwater Inspection

October 11, 2023

Operator: CCRP OPERATING INC - #10665

Location ID: 442375

Inspection Document #: 697504895

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cox 22-B Pad
Location ID: 442375



Photo 1. Photo taken from southeastern location, facing West. Photo illustrates interim reclamation has been performed and perennial vegetation was observed.

Location appears to be recently mowed. There appears to be areas that need additional reseeding.



Photo 2. Photo taken of the Cox 5 well, facing South. Photo illustrates stained soil that needs to be cleaned up and removed.

Inspection Photos
Location Name: Cox 22-B Pad
Location ID: 442375



Photo 3. Photo taken from the secondary containment area. Photo illustrates stained soil that needs to be cleaned up and removed. Also, load out lines were observed being stored inside secondary containment. This would be considered unused equipment.