

# Inspection Photos

Loc: 481042

Operator: BNL (ENTERPRISE) INC

Inspection Date: 10/4/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the access road.



## Inspection Photos



**Photo 2.** Facing west along the access road. Soils appear to be compacted along areas of the road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:481042 | Date: 10/4/2023

## Inspection Photos



**Photo 3.** Facing west toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:481042 | Date: 10/4/2023

## Inspection Photos



**Photo 4.** Center of the location facing west. The vegetation does not appear to be germinating very well at the location. There are undesirable weeds which can be seen in the photo.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:481042 | Date: 10/4/2023

## Inspection Photos



**Photo 5.** Center of the location facing north. The vegetation does not appear to be germinating very well at the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:481042 | Date: 10/4/2023

## Inspection Photos



**Photo 6.** Center of the location facing south. The vegetation does not appear to be germinating very well at the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:481042 | Date: 10/4/2023

## Inspection Photos



**Photo 7.** Facing south toward the undisturbed native grass consisting of Sand dropseed, Blue grama, Galleta grass, among other species.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:481042 | Date: 10/4/2023