

Inspection Photos
Location Name: UPRR 43 Pan AM H #6
Location ID: 318050



Photo 1 Access road completely covered in dead vegetation



Photo 2 Well head WEEDS on location and around equipment

Inspection Photos
Location Name: UPRR 43 Pan AM H #6
Location ID: 318050



Photo 3 Dead vegetation on location and around equipment



Photo 4 Well head sign and dead vegetation around equipment