

# Interim Reclamation and Stormwater Inspection

Date: 10/13/2023

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 428592

Inspection Document #: 708200613

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Pergamos 8-41-7-60  
Location ID: 428592



**Photo 1.** Taken from the access road. Photo illustrates unstabilized soils and evidence of erosion degradation.

Inspection Photos  
Location Name: Pergamos 8-41-7-60  
Location ID: 428592



**Photo 2.** See comments in Photo 1.

Inspection Photos

Location Name: Pergamos 8-41-7-60

Location ID: 428592



**Photo 3.** Taken from the southern location entrance; see comments in Photo 1.

Inspection Photos  
Location Name: Pergamos 8-41-7-60  
Location ID: 428592



**Photo 4.** Continued from Photo 3. Photo illustrates evidence of sediment transport/washout from the production area into the interim areas.



**Photo 5.** Unstabilized soils and erosion degradation on the east side of the location.

Inspection Photos  
Location Name: Pergamos 8-41-7-60  
Location ID: 428592



**Photo 6.** Taken from the topsoil stockpile. The stockpile is predominantly undesirable vegetation (e.g. russian thistle and kochia); additional revegetation activities are required.



**Photo 7.** Center portion of the topsoil stockpile; see comments in Photo 6.

Inspection Photos  
Location Name: Pergamos 8-41-7-60  
Location ID: 428592



**Photo 8.** Southern portion of the topsoil stockpile; see comments in Photo 6.

Inspection Photos  
Location Name: Pergamos 8-41-7-60  
Location ID: 428592



**Photo 9.** Bird nest within vertical separator and absence of wildlife exclusion device.