

# Interim Reclamation and Stormwater Inspection

Date: 10/13/2023

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 423984

Inspection Document #: 708200614

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Pergamos 1-4-44-7-60  
Location ID: 423984



**Photo 1.** Taken near the location entrance. The interim areas are predominantly undesirable vegetation (e.g. kochia and russian thistle), though some desirable vegetation was also observed. Additional weed management and/or reclamation activities are required.



Inspection Photos  
Location Name: Pergamos 1-4-44-7-60  
Location ID: 423984



10/13/23, 10:11 AM  
133° SE  
ECMC

**Photo 2.** Taken from the western portion; see comments in Photo 1.



Inspection Photos  
Location Name: Pergamos 1-4-44-7-60  
Location ID: 423984



**Photo 3.** Sign, wood debris and flare unit foundation remain on location. It does not appear the equipment is being used and must be removed.



Inspection Photos  
Location Name: Pergamos 1-4-44-7-60  
Location ID: 423984



**Photos 4 & 5.** Taken from the topsoil stockpile; undesirable vegetation and bare/exposed soils evident.



Inspection Photos  
Location Name: Pergamos 1-4-44-7-60  
Location ID: 423984



**Photo 6.** Stained soils observed near pump jack mufflers.



Inspection Photos  
Location Name: Pergamos 1-4-44-7-60  
Location ID: 423984



**Photo 7.** Taken from the southeast corner of the location; see comments in Photo 1.



Inspection Photos  
Location Name: Pergamos 1-4-44-7-60  
Location ID: 423984



**Photos 8 & 9.** Stained soils near wellheads.