

Final Reclamation and Stormwater Inspection

Date: 10/13/2023

Operator: STRACHAN EXPLORATION INC - 83130

Location ID: 330622

Inspection Document #: 708200618

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Hill 31-15-8
Location ID: 330622



Photos 1 & 2. Taken near the location entrance. Photo illustrates that the access road and cattle guard have not been removed.

Inspection Photos
Location Name: Hill 31-15-8
Location ID: 330622



Photo 3. Continued from Photos 1 & 2; road base material remains on the access road.

Inspection Photos
Location Name: Hill 31-15-8
Location ID: 330622



Photo 4. Taken from the southern portion of the former tank battery location. Undesirable vegetation (CO List C Noxious Weed-Cheatgrass; russian thistle and kochia) were observed. It should also be noted that some desirable vegetation was also observed throughout the former tank battery location.

Inspection Photos
Location Name: Hill 31-15-8
Location ID: 330622



Photo 5. Taken from the eastern portion of the tank battery location. Non-uniform vegetative cover resulting in areas of bare/exposed soils.

Inspection Photos
Location Name: Hill 31-15-8
Location ID: 330622



Photo 6. Taken from the middle portion of the access road. Undesirable vegetation (CO List C Noxious Weed- Cheatgrass; russian thistle and kochia) was observed on the access road.

Inspection Photos
Location Name: Hill 31-15-8
Location ID: 330622



Photo 7. Taken near the former well location. See comments in Photo 6.

Inspection Photos
Location Name: Hill 31-15-8
Location ID: 330622



Photo 8. Taken from the center portion of the former well. Non-uniform vegetation cover resulting in bare/exposed soils.

Inspection Photos
Location Name: Hill 31-15-8
Location ID: 330622



Photo 9. Taken from the northern portion of the well location; see comments in Photo 8.