

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ARCO-66S96W/29NESE

Location ID: 335184

Date: 10/17/2023



Oct 17, 2023 at 11:07:37
5325 CR-215
Parachute CO 81635
United States



Oct 17, 2023 at 11:08:30
5325 CR-215
Parachute CO 81635
United States

Location Entrance – Photo #06977

Wellheads – Photo #06978

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ARCO-66S96W/29NESE

Location ID: 335184

Date: 10/17/2023



Separators – Photo #06979



Tank Battery – Photo #06981

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ARCO-66S96W/29NESE

Location ID: 335184

Date: 10/17/2023



**Lack of Stabilization/Insufficient Vehicle Tracking BMPs at
Location Entrance/Exit – Photo #06980**