

Interim Reclamation and Stormwater Inspection

October 11, 2023

Operator: CCRP OPERATING INC - #10665

Location ID: 456179

Inspection Document #: 697504902

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: True Ranch Fee/2326 East

Location ID: 456179



Photo 1. Photo taken from the western location, facing Northwest. Photo illustrates interim reclamation has been performed and perennial vegetation was observed and meets Rule 1003 standards.



Photo 2. Photo taken from the western location, facing Southwest. See comments under Photo 1.

Inspection Photos

Location Name: True Ranch Fee/2326 East

Location ID: 456179



Photo 3. Photo taken from the southeastern interim area, facing Southeast. Photo illustrates the Operator has made stormwater erosion repairs.



Photo 4. Photo taken from the southeastern interim area, facing East. Photo illustrates the retention pond is functioning properly and no observed sediment discharge from location.

Inspection Photos

Location Name: True Ranch Fee/2326 East

Location ID: 456179



Photo 5. Photo taken from the western cut slope, facing West. Photo illustrates rill erosion is evident. Operator continues to try and seed the cut slope which is not sufficient.



Photo 6. Photo taken from the western cut slope, facing Northwest. See comments under Photo 5.