

Inspection Photos
Location Name: Blanche-62N62W 20NWNW
Location ID: 327367



Location & Appears to have plant die off

Removed Overgrown Vegetation

Inspection Photos
Location Name: Blanche-62N62W 20NWNW
Location ID: 327367



Removed Overgrown Vegetation

Removed Overgrown Vegetation

Inspection Photos
Location Name: Blanche-62N62W 20NWNW
Location ID: 327367



Removed Overgrown Vegetation & Missing Capacity/ NFPA Placard

Missing Capacity/ NFPA Placard

Inspection Photos
Location Name: Blanche-62N62W 20NWNW
Location ID: 327367



Missing Capacity/ NFPA Placard

Removed Overgrown Vegetation & sign

Inspection Photos
Location Name: Blanche-62N62W 20NWNW
Location ID: 327367



Removed Overgrown Vegetation & Unused panel fence

Appears to have plant die off

Inspection Photos
Location Name: Blanche-62N62W 20NWNW
Location ID: 327367



Appears to have plant die off



Appears to have plant die off