

Inspection Photos

Loc: 308097

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/4/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the location. This gate at the location will need maintenance..



Inspection Photos



Photo 2. Southwest corner of the location facing north. There are some areas bare of vegetation that will need to be interseeded.



Inspection Photos



Photo 3. Facing west along the access road. Soils appear to be compacted along areas of the road.



Inspection Photos



Photo 4. Center of the location facing north. There is vegetation progressing in some areas of the location.



Inspection Photos



Photo 5. Center of the location facing south. There are some areas bare of vegetation that will need to be interseeded.



Inspection Photos



Photo 6. North side of the location facing east. There are some areas bare of vegetation that will need to be interseeded.



Inspection Photos



Photo 7. Facing northwest toward the undisturbed native grass consisting of Sand dropseed, Blue grama, Galleta grass, among other species.

