

# Inspection Photos

Loc: 308238

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/4/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the location. The perennial vegetation has fully establish throughout the east half of the location up to the sign at red arrow.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:308238 | Date: 10/4/2023



## Inspection Photos



**Photo 2.** Center of the location facing west. The area west of the sign has not sufficiently established perennial vegetation.





## Inspection Photos



**Photo 3.** Southwest side of the location facing northeast. The west side of the location has not fully established perennial vegetation and could use additional interseeding.





## Inspection Photos



**Photo 4.** Northwest side of the location facing south. The west side of the location has not fully established perennial vegetation and could use additional interseeding. There is some perennial vegetation establishing shown at red arrow.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:308238 | Date: 10/4/2023



## Inspection Photos



**Photo 5.** Facing northwest toward the undisturbed native grass consisting of Sand dropseed, Blue grama, Galleta grass, among other species.

