

Inspection Photos
Location Name: Nichols 2N, 27N, 28N-5HZ
Location ID: 429782



Photo 1: Wellhead



Photo 2: Unused equipment

Inspection Photos
Location Name: Nichols 2N, 27N, 28N-5HZ
Location ID: 429782



Photo 3: Wellhead



Photo 4: Wellhead



Inspection Photos
Location Name: Nichols 2N, 27N, 28N-5HZ
Location ID: 429782



Energy & Carbon Management Commission
40.15426, -104.68698, 1487.1m, 310°
Oct 18, 2023 11:21:24

Photo 5: Tank Battery Sign



Energy & Carbon Management Commission
40.15415, -104.68699, 1483.6m, 258°
Oct 18, 2023 11:21:44

Photo 6: Centralized Tank Battery



Inspection Photos
Location Name: Nichols 2N, 27N, 28N-5HZ
Location ID: 429782



Photo 7: Disconnected gas meter



Photo 8: Disconnected gas meter

Inspection Photos
Location Name: Nichols 2N, 27N, 28N-5HZ
Location ID: 429782

