

Inspection Photos
Location Name: Nichols 21-8
Location ID: 318070




Photo 1: TA Wellhead



Photo 2: TA Wellhead



Inspection Photos
Location Name: Nichols 21-8
Location ID: 318070



Photo 3: TA Wellhead



Photo 4: TA Wellhead



Inspection Photos
Location Name: Nichols 21-8
Location ID: 318070



Photo 5: Centralized tank battery



Photo 6: Debris

Inspection Photos
Location Name: Nichols 21-8
Location ID: 318070



Photo 7: Debris/weeds



Photo 8: Weeds

Inspection Photos
Location Name: Nichols 21-8
Location ID: 318070



Photo 9: Weeds