

Interim Reclamation and Stormwater Inspection

Date: 10/13/2023

Operator: BISON IV OPERATING LLC - 10670

Location ID: 458635

Inspection Document #: 708200620

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Blue Teal 22C Pad
Location ID: 458635



Photo 1. Taken from the eastern portion of the interim area. The predominant vegetative cover is kochia. Weed management and revegetation activities are required in order to meet Rule 1003 regulations and standards.

Inspection Photos
Location Name: Blue Teal 22C Pad
Location ID: 458635



Photo 2. Taken near the southeast corner of the location. See comments in Photo 1.

Inspection Photos
Location Name: Blue Teal 22C Pad
Location ID: 458635



Photo 3. Taken from the southeastern portion of the location. See comments in Photo 1.

Inspection Photos
Location Name: Blue Teal 22C Pad
Location ID: 458635



Photo 4. Taken on the western side of the location, near the topsoil stockpile. See comments in Photo 1.

Inspection Photos
Location Name: Blue Teal 22C Pad
Location ID: 458635



Photos 5 & 6. Wood debris observed on the west side of the production areas.

Inspection Photos
Location Name: Blue Teal 22C Pad
Location ID: 458635



Photo 7. Unused equipment observed on the west side of the production areas.

Inspection Photos
Location Name: Blue Teal 22C Pad
Location ID: 458635



Photo 8. Taken near the northwest corner of the location. See comments in Photo 1.