

Final Reclamation and Stormwater Inspection

Date: 10/13/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 431544

Inspection Document #: 708200622

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hunt
LF18-62HN Multi
Location ID: 431544



Photo 1. Taken near the entrance. It does not appear any reclamation work has been conducted. Access road/road base material remains on location.



Photo 2. Taken near the former tank battery. It does not appear all surface equipment has been removed with evidence of two meter sheds and flowline risers. Trash and debris, and undesirable vegetation was also observed throughout.

Inspection Photos
Location Name: Hunt
LF18-62HN Multi
Location ID: 431544



Photo 3. Subsidence/hole was observed on the former production facilities. The Operator was immediately contacted and instructed to mark/cover the opening to ensure safe operations.

Inspection Photos
Location Name: Hunt
LF18-62HN Multi
Location ID: 431544



Photo 4. The access road to the well location has not been reclaimed.

Inspection Photos
Location Name: Hunt
LF18-62HN Multi
Location ID: 431544



Photo 5. Taken near the former well. Subsidence/hole was observed. The Operator was immediately contacted and instructed to mark/cover the opening to ensure safe operations.

Inspection Photos
Location Name: Hunt
LF18-62HN Multi
Location ID: 431544



Photo 6. The former well location has not been reclaimed.

Inspection Photos
Location Name: Hunt
LF18-62HN Multi
Location ID: 431544



Photo 7. The former tank battery location has not been reclaimed.

Inspection Photos
Location Name: Hunt
LF18-62HN Multi
Location ID: 431544



Photo 8. Debris/trash and undesirable vegetation observed near the former tank battery facilities.