

WELL NAME: HILL RANCH 32-01 & V, API #: 071-06913, INSP. # 695108688



PHOTO 1: WELL SIGN



**PHOTO 2: LOCATION**





**PHOTO 3: WELLHEAD AND EQUIPMENT**



WGS84  $\pm 16\text{ft}$  37.04599, -104.90654  $\Delta$   $\frac{\text{ft}}{\pm 11\text{ft}}$  8148  $\triangle$   $\frac{\circ, \text{M}}{\pm 16}$  SW222



**PHOTO 4: V WELLHEAD AND EQUIPMENT**



**PHOTO 5: Signs of recent slow leak from wellhead. Salt/mineral buildup is evident on the wellhead ground around wellhead. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals, remove salt/mineral buildup, remove and dispose of impacted material and maintain in good mechanical condition per Rule 608.e. ca date 11-20-2023.**