

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324123

Date: 10/17/2023



Location Entrance – Photo #07028

Wellhead – Photo #07029

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324123

Date: 10/17/2023



Separator – Photo #07030



Tank Battery – Photo #07032

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324123

Date: 10/17/2023



Debris – Photo #07031



Open-Ended Tank Vent – Photo #07033

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324123

Date: 10/17/2023



Lack of Stabilization – Photo #07035



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #07036**