

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

07/11/2023

Document Number:

403460310

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: <u>75000</u>	Contact Person: <u>Carol Byrd</u>
Company Name: <u>BYRD* CAROL W TRUSTEE OF CAROL W BYRD TRUST</u>	Phone: <u>(403) 379-2600</u>
Address: <u>8163 E 131 RD</u>	Fax: <u>()</u>
City: <u>WETUMKA</u> State: <u>OK</u> Zip: <u>74883-6227</u>	Email: <u>april@oilandgasroyalties.com</u>

Identification Information

API Number: 05 - <u> </u> - <u> </u>	OGCC Facility ID: <u>102612</u>	Initial Form 19 or 27 Document number: <u> </u>
Facility Name: <u>LYLE CHANDLER</u>	Facility Number: <u> </u>	Facility Type: <u>PIT</u>
Location QtrQtr: <u>NESE</u>	Section: <u>10</u>	Township: <u>2N</u>
	County: <u>WASHINGTON</u>	Range: <u>49W</u>
		Meridian: <u>6</u>
		Field Name: <u>HYDE</u>
Federal, Indian or State Lease Number: <u> </u>		

Information Submitted By:

Company Name: <u>CGRS, Inc</u>	Agent Name: <u>Lauren Glazer</u>	Title: <u>Staff Scientist</u>
Phone Number: <u>800-288-2657</u>	Email: <u>lglazier@cgrs.com</u>	

Rule 909.J Inspection Information

Date the Pit was Inspected 06/01/2023

On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: <u>234894</u>	Facility Name: <u>LYLE CHANDLER 1</u>	Facility Type: <u> </u>
Location: QtrQtr: <u>NESE</u>	Sec: <u>10</u>	Twp: <u>2N</u>
	County Name: <u>WASHINGTON</u>	Range: <u>49W</u>
	Latitude: <u>40.154260</u>	Meridian: <u>6</u>
	Longitude: <u>-102.833370</u>	

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: <u>111500</u>	Document Name: <u>EDD</u>	File Name: <u>Lyle Chandler EDD.xls</u>
SampleType: <u> </u>	Matrix: <u> </u>	
Facility ID: <u>234894</u>	Sample ID: <u>650170</u>	Sample Name: <u>Carol Byrd- Lyle Chandler</u>
	Collection Point: <u>SEP</u>	Sample Date: <u>06/01/2023</u>
	Matrix: <u>WATER</u>	Pre Post: <u>Rule 909.j initial sample</u>
Project Number: <u>234894</u>	Remediation Number: <u> </u>	Complaint Number: <u> </u>
		NOAV Number: <u> </u>
Inspection Number: <u> </u>	Spill Number: <u> </u>	Laboratory: <u> </u>
		Lab Sample ID: <u>AA01425</u>

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
234894	403460316	Lyle Chandler Lab Report.pdf	Analytical Laboratory Report	PDF
234894	403460315	Lyle Chandler Field Data (1).pdf	Field Data Report	PDF

Sample COGCC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
650170	121-07036	LYLE CHANDLER 1	

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	10/24/2023
Total: 1 comment(s)		