

Inspection Photos

Location Name: John A. Kunzman 1, 2, 3, 4, & 43-6 TB

Location ID: 317729



Photo 1 Location.

Photo 2 TB sign.

Inspection Photos

Location Name: John A. Kunzman 1, 2, 3, 4, & 43-6 TB

Location ID: 317729




Photo 3 TB inside berm is near level.



Photo 4 Stained soil by load out valve.

Inspection Photos
Location Name: John A. Kunzman 1, 2, 3, 4, & 43-6 TB
Location ID: 317729



Photo 5 Unmarked flow lines.

Photo 6 Stained soil by crude oil valve back side.

Inspection Photos

Location Name: John A. Kunzman 1, 2, 3, 4, & 43-6 TB

Location ID: 317729



Photo 7 TB inside berm is near level.

Photo 8 Unused auxillary pump.

Inspection Photos

Location Name: John A. Kunzman 1, 2, 3, 4, & 43-6 TB

Location ID: 317729



Colorado Energy & Carbon Management Commission
40.16036, -104.80274, 4830.6ft
10/24/2023 13:51:27



Colorado Energy & Carbon Management Commission
40.16037, -104.80276, 4832.7ft
10/24/2023 13:51:35

Photo 9 Horizontal Heated Separator.

Photo 10 Flow lines .

Inspection Photos
Location Name: John A. Kunzman 1, 2, 3, 4, & 43-6 TB
Location ID: 317729



Photo 11 Unused Gas Meter Run.

Photo 12 Unused Gas Meter Run.

Inspection Photos

Location Name: John A. Kunzman 1, 2, 3, 4, & 43-6 TB

Location ID: 317729



Colorado Energy & Carbon Management Commission
40.16047, -104.80284, 4833.5ft
10/24/2023 13:52:55



Colorado Energy & Carbon Management Commission
40.16055, -104.80291, 4839.4ft
10/24/2023 13:54:00

Photo 13 Gas Meter Run.

Photo 14 Unused unmarked flow lines.

Inspection Photos

Location Name: John A. Kunzman 1, 2, 3, 4, & 43-6 TB

Location ID: 317729



Colorado Energy & Carbon Management Commission
40 16052, -104.80291, 4831.4ft
10/24/2023 13:53:39



Colorado Energy & Carbon Management Commission
40 16066, -104.80296, 4836.8ft
10/24/2023 13:54:36

Photo 15 Unmarked flow line.

Photo 16 Unused flow line.

Inspection Photos

Location Name: John A. Kunzman 1, 2, 3, 4, & 43-6 TB

Location ID: 317729



Photo 17 Produced Water vessel.



Photo 18 Unmarked excavation between the TB & WH location with visible flow line.

Inspection Photos

Location Name: John A. Kunzman 1, 2, 3, 4, & 43-6 TB

Location ID: 317729



Photo 19 Unmarked excavation between the TB & WH location with visible flow line.



Photo 20 Unmarked excavation between the TB & WH location with visible flow line.