

Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES J13W Pad

Location #: 334558



Photo # 4262 From entrance to location




Photo # 4263 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES J13W Pad

Location #: 334558



Photo # 4264 Location



Photo # 4265 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES J13W Pad

Location #: 334558



Photo # 4266 Location

Photo # 4267 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC ROLES J13W Pad
Location #: 334558



Photo # 4268 Location



Photo # 4269 Weeds

Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES J13W Pad

Location #: 334558



Photo # 4270 Wildlife BMP's around excavation areas need maintenance



Photo # 4271 Wildlife BMP's around excavation areas need maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES J13W Pad

Location #: 334558



Photo # 4272 Wildlife BMP's around excavation areas need maintenance



Photo # 4273 Wildlife BMP's around excavation areas need maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES J13W Pad

Location #: 334558



Photo # 4274 Weeds