

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2023

Submitted Date:

10/25/2023

Document Number:

701007571**FIELD INSPECTION FORM**Loc ID 310948 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 10730Name of Operator: CWC PETRO LLCAddress: 6957 #A ISABELL LNCity: ARVADA State: CO Zip: 80007**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name       | Phone          | Email                | Comment |
|--------------------|----------------|----------------------|---------|
| Clark, Christopher | (303) 519-7870 | cwclark@cwcpetro.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 297034      | WELL | PR     | 11/01/2020  | GW         | 125-11341 | LENDEL 1-44   | PR          |

**General Comment:**[Routine Inspection](#)

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Trail through farm ground |       |  |
| Corrective Action: |                           | Date: |  |

Overall Good: ☒

|                      |                        |       |  |
|----------------------|------------------------|-------|--|
| <b>Signs/Marker:</b> |                        |       |  |
| Type                 | WELLHEAD               |       |  |
| Comment:             | Lease sign by wellhead |       |  |
| Corrective Action:   |                        | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Fencing/:</b>   |  |       |  |
| Type               | WELLHEAD                                   |       |  |
| Comment:           | Metal panels around wellhead and meter run |       |  |
| Corrective Action: |  | Date: |  |

|                           |  |       |                 |
|---------------------------|--|-------|-----------------|
| <b>Equipment:</b>         |  |       | corrective date |
| Type: Ancillary equipment | # 2                                    |       |                 |
| Comment:                  | Electric panel and telemetry equipment |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Gas Meter Run       | # 1                                    |       |                 |
| Comment:                  |  |       |                 |
| Corrective Action:        |  | Date: |                 |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities |                              |       |      |             |           |         |    |               |    |
|----------------------|------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 297034                       | Type: | WELL | API Number: | 125-11341 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                              |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Casing production |       |      |             |           |         |    |               |    |
| Corrective Action:   |                              |       |      | Date:       |           |         |    |               |    |

Reclamation - Storm Water - Pit

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other            | Pass            | Other                   | Pass                  |               |                          |         |

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT