

Inspection Photos  
Location: Sheep Mountain Unit 12-2-E  
Facility ID: 324505



Photo 1 –Wellhead Placard

Photo 2 – Historical Wellhead location, Well is under an open remediation. Remediation # 24088


**Inspection Photos**  
**Location: Sheep Mountain Unit 12-2-E**  
**Facility ID: 324505**



**Photo 3 – Wellhead, Form 27 Document # 403489470, States; Operator will continue quarterly reporting until the site investigation is complete and table 915-1 standards are met within the remediation area**

**Photo 4 – Contaminated Material**

Inspection Photos  
Location: Sheep Mountain Unit 12-2-E  
Facility ID: 324505



**Photo 5 – Contaminated Material**

**Photo 6 – Pit, Pit ID 115231, Remediation # 28882**

**Inspection Photos**  
**Location: Sheep Mountain Unit 12-2-E**  
**Facility ID: 324505**



**Photo 7 – Pit, Pit ID 115231, Remediation # 28882**