

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM MOUNTAIN RANCH J17E Pad

Location # 334872



Photo # 4408 From entrance to location



Photo # 4409 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM MOUNTAIN RANCH J17E Pad

Location # 334872




Photo # 4410 Location

Photo # 4411 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM MOUNTAIN RANCH J17E Pad

Location # 334872



Photo # 4412 Location



Photo # 4413 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM MOUNTAIN RANCH J17E Pad

Location # 334872



Photo # 4414 Location



Photo # 4415 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM MOUNTAIN RANCH J17E Pad

Location # 334872



Photo # 4416 Location



Photo # 4417 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM MOUNTAIN RANCH J17E Pad

Location # 334872



Photo # 4418 Unused equipment



Photo # 4419 Bracket on little joe regulator broken

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM MOUNTAIN RANCH J17E Pad

Location # 334872



Photo # 4420 Bracket on little joe regulator broken



Photo # 4421 Bracket on little joe regulator broken