

Inspection Photos
Operator: SCOUT ENERGY MANAGEMENT LLC - 10779
Location Name: FEE #162Y
Location ID: 430099 API #: 05-103-11945
Inspection Date: 10/26/2023 Inspection Doc#: 693806502



10.26.2023 10:16

Injection well during MIT

Click here to request the form
Oil and Gas Conservation Commission
MECHANICAL TESTING REPORT

Well Information:
 Well Name: Webster Well ID: 5948-6410
 Well Type: Injection Well
 Well Status: Active
 Well Depth: 5851.43
 Well Completion: 15.0
 Well Completion Date: 10/26/2023
 Well Completion By: 1380
 Well Completion Date: 10/26/2023
 Well Completion By: 1380

Test Results:
 Test Type: MIT
 Test Date: 10/26/2023
 Test Results: 15.0
 Test Results Date: 10/26/2023
 Test Results By: 1380

Signatures:
 Inspector: [Signature] Date: 10-26-23
 Operator: [Signature] Date: 10-26-23

Conditions of Approval:
 I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

10.26.2023 10:40

Form 21 field copy