

Inspection Photos

Loc: 309227

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 10/26/2023

County: LAS ANIMAS



Inspection Photos



Photo 1. The two culvert crossing the drainage remain filled in with sediment.



Inspection Photos



Photo 2. The two culvert crossing the drainage remain filled in with sediment.



Inspection Photos



Photo 3. Facing southwest along the access road.



Inspection Photos



Photo 4. Facing northwest toward the location.



Inspection Photos



Photo 5. The pit was excavated and appears to be in process for closure.

