

Inspection Photos

Loc: 308242

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 10/26/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the access road. There is erosion that needs to be repaired.



Inspection Photos



Photo 1. Facing northeast at the location.

