

Inspection Photos
Location Name: Elton N Miller 2
Location ID:318286



Photo 1 well head and equipment



Photo 2 well head and equipment

Inspection Photos
Location Name: Elton N Miller 2
Location ID:318286



Photo 3 mechanical issues and stained soil



Photo 4 mechanical issues and stained soil

