

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC BENTLY 11-44 (PP11) Pad
Location #: 324238



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**

Section/Township/Range: 11 7S95W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC BENTLY 11-44 (PP11) Pad
Location #: 324238



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC BENTLY 11-44 (PP11) Pad
Location #: 324238



Photo # 3987 Erosion & transport of sediment off location



Photo # 3988 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC BENTLY 11-44 (PP11) Pad
Location #: 324238



Photo # 3989 Erosion & transport of sediment off location



Photo # 3990 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC BENTLY 11-44 (PP11) Pad
Location #: 324238



Photo # 3991 Erosion & transport of sediment off location