

Operator: EXTRACTION OIL & GAS INC

Location Name: Breniman 16-B

Loc ID: 439436

Inspection: 697008222



Exhibit A

CA: Maintenance tank lacks contents placards, see attached photo. Install sign to comply with Rule 605.h.

CA Resolution: The Field has appropriately installed contents signage on the Maintenance Tank to comply with Rule 605.h.