

Operator: CIVITAS NORTH LLC
Location Name: Hunt 8-60 17B
Loc ID: 457475
Inspection: 708200625



Exhibit A

CA: Trash was observed throughout the interim areas. Refer to inspection photos for examples. Comply with Rule 606. The location will remain out of compliance until the corrective action has been resolved.

CA Resolution: The Field has appropriately cleaned and cleared trash and weed debris from location to comply with Rule 606.