

# Final Reclamation and Stormwater Inspection

Date: 10/17/2023

Operator: Whiting Oil & Gas Corporation - 96155

Location ID: 305647

Inspection Document #: 713900037

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Photo 1.** Photo at the access road entrance facing Southeast. The photo illustrates the entrance has bare soil and tumbleweeds (Kochia and Russian thistle).



Inspection Photos  
Location Name: Maddy 2  
Location ID: 305647



**Photo 2.** The photo was taken along the access road facing East. The photo illustrates the road is compacted and incised as well having large areas of bare soil and undesirable plant establishment.



Inspection Photos  
Location Name: Maddy 2  
Location ID: 305647



**Photo 3.** The photo was taken at the center of the Maddy pad facing Southeast. The photo illustrates bare soil across the location.





**Photo 4.** The photo was taken just North of the well location facing Northeast. The photo again illustrates large areas of bare soil in the Northern part of the Maddy pad.



Inspection Photos  
Location Name: Maddy 2  
Location ID: 305647



**Photo 5.** The reference photo was taken in the center of the Maddy pad facing East.