

Interim Reclamation and Stormwater Inspection

October 24, 2023

Operator: NOBLE ENERGY INC - #100322

Location ID: 431520

Inspection Document #: 697504915

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: A30-01 Pad
Location ID: 431520



Photo 1. Photo taken from the northern production facility, facing South. Photo illustrates erosion traveling off the fill slope of the production facility without sufficient BMPs along the perimeter of location.



Photo 2. Photo taken from the northern production facility, facing South. See comments under Photo 1.

Inspection Photos
Location Name: A30-01 Pad
Location ID: 431520




Photo 3. Photo taken from the northeastern production facility, facing North. See comments under Photo 1.



Photo 4. Photo taken from the northeastern production facility, facing Northeast. See comments under Photo 1.



Inspection Photos
Location Name: A30-01 Pad
Location ID: 431520



Photo 5. Photo taken from the well location, facing North. Photo illustrates the Operator is in process of plugging operations.