

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRASS MESA RANCH 9-2 (B9W) Pad

Location #: 334566



Photo # 5018 From entrance to location



Photo # 5019 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRASS MESA RANCH 9-2 (B9W) Pad

Location #: 334566



Photo # 5020 Location



Photo # 5021 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRASS MESA RANCH 9-2 (B9W) Pad

Location #: 334566



Photo # 5022 Location



Photo # 5023 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC GRASS MESA RANCH 9-2 (B9W) Pad

Location #: 334566



Photo # 5024 Open ended load line