

Final Reclamation Inspection

October 24, 2023

Operator: PHOENIX RESOURCES LLC - 10691

Location ID: 310112

Inspection Document #: 697504919

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STATE #2
Location ID: 310112



Photo 1. Photo taken from a portion of the access road ~225' south of the southern location, facing South. Photo illustrates the access road has not been reclaimed, erosion is evident, and unmanaged weeds (kochia and russian thistle) observed along the access road.



Photo 2. Photo taken from the southeastern location, facing West. Photo illustrates the location has not been reclaimed, debris, and unmanaged weeds observed throughout the location.

Inspection Photos
Location Name: STATE #2
Location ID: 310112



Photo 3. Photo taken from a portion of the location illustrating guy line anchors have not been removed.



Photo 4. Photo taken from a portion of the location illustrating debris left on location.

Inspection Photos
Location Name: STATE #2
Location ID: 310112



Photo 5. Reference photo taken east of the location, facing East.