

Final Reclamation Inspection

October 24, 2023

Operator: PHOENIX RESOURCES LLC - 10691

Location ID: 330493

Inspection Document #: 697504921

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MCGAHEY OIL, LLC STATE 1A
Location ID: 330493




Photo 1. Aerial imagery illustrates the well location and associated offsite tank battery.



Inspection Photos

Location Name: MCGAHEY OIL, LLC STATE 1A

Location ID: 330493



Photo 2. Photo taken from the southern portion of the access road, facing North. Photo illustrates the access road has not been reclaimed and unmanaged weeds (kochia and russian thistle) observed along the access road.



Photo 3. Photo taken from the well location, facing West. Photo illustrates the location has not been reclaimed, fencing remains, and unmanaged weeds observed throughout the location.



Inspection Photos
Location Name: MCGAHEY OIL, LLC STATE 1A
Location ID: 330493



Photo 4. Photo taken from a portion of the location illustrating guy line anchors have not been removed.



Photo 5. Photo taken from the northern well location, facing South. See comments under Photo 3.

Inspection Photos

Location Name: MCGAHEY OIL, LLC STATE 1A

Location ID: 330493



Photo 6. Photo taken from the associated offsite tank battery, facing West. See comments under Photo 3.



Photo 7. Reference photo taken west of the location, facing East.

