

## Inspection Photos

Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad

Location #: 334892



**Photo # 4567 From entrance to location**



**Photo # 4568 From entrance to location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad**  
**Location #: 334892**



**Photo # 4569 Location**

**Photo # 4570 Location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad**  
**Location #: 334892**



**Photo # 4571 Location**



**Photo # 4572 Location**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad

Location #: 334892



**Photo # 4573 Location**



**Photo # 4574 Location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad**  
**Location #: 334892**



**Photo # 4575 Location**



**Photo # 4576 Location**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad

Location #: 334892



Photo # 4577 Open ended port on production tank/wildlife hazard



Photo # 4578 Corrosion & hole in top of production/open ended port/wildlife hazards

## Inspection Photos

Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad

Location #: 334892



**Photo # 4579 Tank has corroded & failed/hole in tank/wildlife hazard**



**Photo # 4580 Debris**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad

Location #: 334892



Photo # 4581 Debris



Photo # 4582 Debris

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC G32NEB/NED Pad**  
**Location #: 334892**



**Photo # 4583 Debris**



**Photo # 4584 Unused equipment**