

Inspection Photos
Location Name: Cook 8-9
Location ID: 305662



Photo 1: Unused equipment

Photo 2: Access road to wellhead

Inspection Photos
Location Name: Cook 8-9
Location ID: 305662



Energy & Carbon Management Commission
40.15451, -104.66114, 1461.9m, 3°
Nov 1, 2023 12:07:17



Energy & Carbon Management Commission
40.15447, -104.66115, 1468.7m, 307°
Nov 1, 2023 12:07:25

Photo 3: Wellhead Sign

Photo 4: TA Wellhead

Inspection Photos
Location Name: Cook 8-9
Location ID: 305662



Photo 5: Location

Photo 6: Tank Battery

Inspection Photos
Location Name: Cook 8-9
Location ID: 305662



Photo 7: Unused equipment

Photo 8: Damaged earth berm