

Inspection Photos
Location: Bantini 11-25 and Bantini 11-25 TR
Facility ID: 333456



Photo 1 –Well Site Placard



Photo 2 – Bantini 11-25 No pit observed

Inspection Photos
Location: Bantini 11-25 and Bantini 11-25 TR
Facility ID: 333456



Photo 3 – Bantini 11-25 TR no pit observed

