

# Inspection Photos

Loc: 321139

Operator: **LORENTZ OIL & GAS LLC**

Inspection Date: 10/31/2023

County: BACA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest at the abandoned wellsite. This are bare of vegetation is where the well was located. There are likely impacted soils preventing vegetation growth.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:321139 | Date: 10/31/2023

## Inspection Photos



**Photo 2.** South side of the location facing northwest. This area with no vegetation is approximately 120'x80'. There are likely impacted soils preventing vegetation growth



## Inspection Photos



**Photo 3.** North side of the location facing southeast. This area with no vegetation is approximately 120'x80'. There are likely impacted soils preventing vegetation growth



## Inspection Photos



**Photo 4.** Facing east toward the surrounding reference area which consists of native Blue grama, Sand drpseed, ect.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321139 | Date: 10/31/2023