

Inspection Photos
Location Name: Thomason 4-15
Location ID: 318744



Energy & Carbon Management Commission
40.14465, -104.65617, 1470.4m, 169°
Nov 3, 2023 11:06:15



Energy & Carbon Management Commission
40.14376, -104.65607, 1478.8m, 129°
Nov 3, 2023 11:00:00

Photo 1: Location

Photo 2: Tank Battery

Inspection Photos
Location Name: Thomason 4-15
Location ID: 318744



Photo 3: TA Wellhead

Photo 4: TA Wellhead

Inspection Photos
Location Name: Thomason 4-15
Location ID: 318744



Photo 5: TA Wellhead

Photo 6: TA Wellhead

Inspection Photos
Location Name: Thomason 4-15
Location ID: 318744



Photo 9: Disconnected gas meter



Photo 10: Not legible capacity signage

Inspection Photos
Location Name: Thomason 4-15
Location ID: 318744



Photo 11: Debris



Photo 12: Debris

Inspection Photos
Location Name: Thomason 4-15
Location ID: 318744



Photo 13: Debris

Photo 14: Debris

Inspection Photos
Location Name: Thomason 4-15
Location ID: 318744



Photo 15: Debris

Photo 16: Debris