

Caerus Piceance LLC  
Bentley 11-33  
Location ID: 324137



Entrance to location



Sign at tank battery

Caerus Piceance LLC  
Bentley 11-33  
Location ID: 324137



As signs are replaced additional information is required



Rain cap missing





**Caerus Piceance LLC  
Bentley 11-33  
Location ID: 324137**



**Location from Southwest corner**



**Location from Southeast corner**



**Caerus Piceance LLC  
Bentley 11-33  
Location ID: 324137**



**Location from Northeast corner**



**Location from Northwest corner**