

Caerus Piceance LLC
Bentley-67S95W 11SWNE
Location ID: 334625




No visible display of gas calibration



As signs are replaced additional information will be required

Caerus Piceance LLC
Bentley-67S95W 11SWNE
Location ID: 334625



Venting



Open to wildlife

Caerus Piceance LLC
Bentley-67S95W 11SWNE
Location ID: 334625



Sign at tank battery



Conflicting labels

Caerus Piceance LLC
Bentley-67S95W 11SWNE
Location ID: 334625



Unused equipment. Out of Service.



Hole in tank

Caerus Piceance LLC
Bentley-67S95W 11SWNE
Location ID: 334625



Hole in liner



Hole in liner


Caerus Piceance LLC
Bentley-67S95W 11SWNE
Location ID: 334625



Debris

Debris

**Caerus Piceance LLC
Bentley-67S95W 11SWNE
Location ID: 334625**




Location from Southeast corner. Entrance to location.



Location from Southwest corner

**Caerus Piceance LLC
Bentley-67S95W 11SWNE
Location ID: 334625**



Location from Northeast corner

Location from Northwest corner