

Inspection Photos
Location Name: Sprague 42-9
Location ID: 311425



Photo 1 Location.




Photo 2 WH sign.



Inspection Photos
Location Name: Sprague 42-9
Location ID: 311425



Photo 3 WH..



Photo 4 undesirable vegetation around WH and fencing.