

# Final Reclamation Inspection

October 12th, 2023

Operator: Enduring Resources LLC - 10663

Location ID: 326637

Inspection Document #: 714000092

La Plata County, CO

Township: SENE 1 34N 9W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: St. Ours 1-3  
Location ID: 326637



**Photo 1.** View of the well disturbance taken from the entrance facing center.



API #: 067-08501



Inspection Photos  
Location Name: St. Ours 1-3  
Location ID: 326637



**Photo 2.** View of the western interim reclamation area facing south.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08501





10/12/23  
+37.238662,-107.798595  
39° NE

**Photo 3.** View of the equipment stored on the northern edge of the disturbance.





Inspection Photos  
Location Name: St. Ours 1-3  
Location ID: 326637



**Photo 4.** Smooth brome, crested wheatgrass and rabbitbrush.

